ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0099, W0101, W0050, W0117, W0044, W0048, W0046, W	NA, Om Shakthi Lyt 1st Crs	VINAYAKA LAYOUT
Segment No.	**Total Length (m)**	
5/S-W0099/S012656	508.13	

Segment Detaiis

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	331.48	77.613734	13.121525	77.613321	13.118557	M0014	W0058
2	97.71	77.613085	13.121607	77.612998	13.120728	M0014	DEAD END
3	78.94	77.612793	13.121634	77.612693	13.120927	M0014	W0097

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Development and improvements to road & drain in main road and cross roads in ward no 05 Jakkur Byatarayanapura Sub-Division Yelahanka zone	5000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Development and improvements to road & drain in main road and cross roads in ward no 05 Jakkur Byatarayanapura Sub-Division Yelahanka zone	005-16-000036
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/01/2016-17	20/04/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
20/04/2016	19/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

9611118200

Field Inspection Details

Number of Trees	Any Other Information	Name
23		chandrakanth
Date of Inspection	**Remarks**	
12/07/2016	completed	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0099, W0101, W0050, W0117,

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	12/07/2016	11/08/2016	completed
SE	VASU K M	12/07/2016	11/08/2016	completed
EE	YARAPPA REDDY	12/07/2016	11/08/2016	completed
AEE	J N LOKESH	12/07/2016	11/08/2016	completed
AE	CHANDRAKANTH	12/07/2016	11/08/2016	completed
AE	CHANDRAKANTH	12/07/2016	11/08/2016	completed

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0099, W0101, W0050, W0117,